



**JAMAN SOUTH MUNICIPAL
ASSEMBLY**



P. O. Box 5, Drobo - B/R, Ghana

Digital Address: B1-0003-2774

Kindly quote this number and date on all correspondence

Your Ref No.....

Our Ref No: JSMA.10/30/05

Date: 30/01/2026

**SUBMISSION OF REPORT ON SANITATION IMPROVEMENT PACKAGE (SIP),
DISINFECTION AND FUMIGATION, 2025**

I hereby submit the above report for your study and necessary action.

Thank you.

**CHRISTOPHETR FRIMPONG
ENVIRONMENTAL HEALTH ANALYST**

**THE MUNICIPAL CHIEF EXECUTIVE
JAMAN SOUTH MUNICIPAL ASSEMBLY
DROBO**

Cc:

**THE REGIONAL ENV. HEALTH DIRECTOR
BONO REGION
SUNYANI**



Republic of Ghana

Bono Region

Tel: (+233) 035 2291387
Email: info@jsma.gov.gh
Website: www.jsma.gov.gh

REPORT ON SANITATION IMPROVEMENT PACKAGE (SIP), DISINFECTION AND FUMIGATION.

INTRODUCTION

This report covers all activities on Sanitation Improvement Package (SIP), Disinfection and Fumigation carried out by the Zoom lion Ghana Limited under the supervision of the Environmental Health and Sanitation Unit.

ACTIVITIES CARRIED OUT

1. Daily lifting of communal containers to final solid waste disposal site.
2. Periodic disinfection and fumigation of:
 - Final solid waste disposal site-Faaman
 - Communal container sites
 - Official bungalows and quarters of the Assembly
 - Public toilets
 - Drains and gutters

SANITATION IMPROVEMENT PACKAGE (SIP) ACTIVITIES

During the period under review, refuse was collected from the communal container sites to the final disposal sites at Faaman by the skip truck.

The table below represents the communal container sites and the refuse lifted in the municipality to the final disposal sites.

S/N	Container site	No. of containers at site	Number of times lifted	Weight in tonnes
1	Drobo main market area	2	288	1,728
2	Sakora	3	1008	12,096
3	Krupiase	1	216	2,592
4	Japekrom Abayonyom	1	204	2,448
5	Japekrom Newtown A (Water works)	1	156	936



Republic of Ghana

Bono Region

Tel: (+233) 035 2291387
Email: info@jsma.gov.gh
Website: www.jsma.gov.gh

6	KBK	1	216	1,296
7	Gonasua	1	156	936
8	OLP-school	1	144	864
9	Total	11	2,388	22,896

During this period, a total of Twenty-two thousand, eight hundred and ninety-six (22,896) tonnes of solid waste was lifted by Zoomlion to the final disposal site at Faaman.

DISINFECTION AND FUMIGATION ACTIVITIES

Measures were put in place during the period under review to control vectors of public health importance in the Municipality.

The Disinfection and Fumigation exercises were carried out at places such as:

- Final solid waste disposal site-Faaman
- Communal container sites
- Official bungalows and quarters of the Assembly
- Public toilets

10. EQUIPMENT

The following have been identified as critical requirements for Sanitation Improvement Package (SIP), Disinfection and Fumigation to enhance environmental sanitation services in the Municipality.

Skip truck

Motorized spraying machines

11. CHALLENGES

1. The delay by zoom lion in lifting containers caused spillage of refuse at some communal container sites.

RECOMMENDATION

Frequent lifting of the communal containers to final solid waste disposal sites to prevent spillage.

CONCLUSION




Republic of Ghana

Bono Region

Tel: (+233) 035 2291387
 Email: info@jsma.gov.gh
 Website: www.jsma.gov.gh

Sanitation Improvement Package (SIP), Disinfection and Fumigation activities were done successfully for the period under review.



Pictures of the Sanitation Improvement Package (SIP) Disinfection and Fumigation activities attached.



Republic of Ghana

Bono Region

Tel: (+233) 035 2291387
Email: info@jsma.gov.gh
Website: www.jsma.gov.gh



Republic of Ghana

Bono Region

Tel: (+233) 035 2291387
Email: info@jsma.gov.gh
Website: www.jsma.gov.gh